

**GOVERNMENT OF KARNATAKA
PUBLIC WORKS DEPARTMENT**
Office of the Assistant Executive Engineer, No. 2 Buildings Sub-Division, Mysuru

No.: Govt.-PWD: No.2 Bldg. Sub-Div.: 2026-27

456-57 / 05-08-2026

To,

**Mycas International School
SS Nagar, Bannimantap,
Mysuru.**

Respected Sir/Madam,

Subject: Regarding issuance of the building safety certificate for Mycas International School, SS Nagar, Bannimantap, Mysuru.

References:

1. Government Circular No.: PWD 59 BGD 2019, dated 07.05.2022.
2. Government Circular No.: PWD 59 BGD 2019, dated 25.09.2024.
3. Your office letter dated 17.07.2026.
4. Letter dated 30.07.2026 from Buildpoint Constructions and Technologies Pvt. Ltd., Mysuru.
5. Office of the District Fire Office No.: 100(3)/RCC/FSO/DFO//BFS/MYS2026-27, dated 13.07.2026.

With reference to the subject mentioned above, in the letter referred to at Reference 3, the Head Master, Mycas International School, SS Nagar, Bannimantap, Mysuru, has requested issuance of a building safety certificate for the school building. Accordingly, the said building was inspected on 12.06.2026 and it was observed that the building is in a sound condition.

Further, with reference to References 4 and 5, the Government fee related to fire safety has been paid. The documents submitted were examined, and the permanent water supply and drinking water arrangements as well as the fire-fighting arrangements of the school building were inspected. The following provisions/observations apply to the building:

- 1) The school building consists of a framed structure comprising the ground floor, first floor and second floor.
- 2) The said building was completed during the year 1992-93, and the building completion certificate has been submitted. Separate toilet facilities have been provided for boys and girls in the school.
- 3) Buildpoint Constructions and Technologies Pvt. Ltd., Mysuru, conducted an Ultrasonic Pulse Velocity Test and Rebound Hammer Test in relation to the structural safety of the building and submitted the report. As per the report, the building was found to be of good quality.
- 4) The school building shall be maintained properly from time to time by carrying out the necessary repairs.



-:2:-

- 5) The school management has obtained a No Objection Certificate (NOC) from the Fire Department and has already installed the equipment prescribed by the Fire Department. Necessary steps shall be taken to provide training to the school staff and students regarding the precautionary measures to be followed in the event of a fire accident, and adequate water facilities shall be provided.
- 6) The waste and debris accumulated on the roof of the school building shall be cleaned periodically, and the rainwater pipe spouts shall be kept free from blockage.
- 7) Necessary safety rules shall be implemented within the premises of the school building.
- 8) During the validity period of the School Safety Certificate, if any rooms in the school are expanded or renovated, a fresh Safety Certificate shall be obtained.
- 9) If any changes are proposed to be made to the upper floor of the school building, appropriate technical advice shall be obtained and necessary action shall be taken keeping the safety and welfare of the children in mind.
- 10) The school premises shall be kept clean, the toilets shall be maintained hygienically, and necessary measures shall be taken to prevent water leakage from the roof during the rainy season.

The Head Master, Mycas International School, S.S. Nagar, Bannimantap, Mysuru, has submitted Demand Drafts towards the prescribed fees for school/college buildings in urban areas, as per the order of the Government of Karnataka, Department of Primary Education, vide Circular No. ED: 43: PGC: 2022 dated 18.05.2022, amounting to ₹5,000/- and GST of ₹900/-. The Demand Drafts bearing Nos. 343617 and 343618, drawn on State Bank of Canara, Mysuru Branch, dated 22.07.2026, have been submitted to this office.

Upon verification of all the documents submitted and inspection of the said building, it has been found that the building is structurally sound. Subject to the condition that the building is properly maintained and necessary repairs are carried out from time to time, the Building Safety Certificate is hereby issued and shall remain valid for a period of 03 years from the date of issue.

Yours faithfully,

ನಿಮ್ಮ ಕಂಡು ಬಂದಿರುವುದು. ಕಟ್ಟಡವನ್ನು ಕಾಲಕಾಲಕ್ಕೆ ನಿರ್ವಹಿಸಿ
ಇದಕ್ಕೆ ಈ ದಿನಾಂಕದಿಂದ 03 ವರ್ಷದವರೆಗೆ ಜಾರಿಯಲ್ಲಿರುವಂತೆ ಕಟ್ಟಡ

ಕನ್ನಡ ನಿರ್ದೇಶಕರು.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ.

ನಂ-2 ಕಟ್ಟಡಗಳ ಉಪ ವಿಭಾಗ, ಮೈಸೂರು.

Assistant Executive Engineer,

Public Works Department,

No. 2 Buildings Sub-Division, Mysuru.



the Original Document in KANNA DA
is translated to ENGLISH
and the translation is Verified by me
as true and Correct

Notary Mysuru

12 AUG 2026